BILAGA 1
Till Idrottsnämnden

Skrivelse angående Eriksdalshallen

Eriksdalshallen på Södermalm är idag inte godkänd för internationellt spel. Hammarby Handboll har tagit kontakt med European Handball Federation för att få information om vilka förändringar av hallen som skulle krävas för att den skulle kunna bli godkänd. European Handball Federation svar innehåller de punkter som behöver åtgärdas, brevet bifogas skrivelsen.

Med anledning av ovanstående vill jag ge idrottsförvaltningen i uppdrag att undersöka och redovisa möjligheten att göra Eriksdalshallen godkänd för internationellt spel.

Stockholm den 13 februari 2007

Jari Visshed (s)

Vice ordförande Idrottsnämnden



EUROPEAN HANDBALL FEDERATION
EUROPAISCHE HANDBALL FODERATION
FEDERATION EUROPEENNE DE HANDBALL
TOTAL T

411 / 683 /0

06 1003

1940

E-mail: johan@offentligajobb.se

Vienna, 11th August 2006

Report club site-inspection

Dear Mr. Hornhammer,

Dear Johan,

Hammarby IF

Sweden

Pligguagen 41, 2tr 12639 Hägersten

After carrying out the EHF site-inspection in Stockholm/Hammarby (Ericsdalshallen) on 7th August 2006 please find below now the remarks concerning the necessary improvements for Ericsdalshallen. The inspection report has been evaluated and a feedback concerning the basic demands on the currently valid rules and regulations is given in the following in order to establish the necessary contact to the responsible authorities asap.

Playing hall

The playing hall Ericsdalshallen (Ringv.68-70, 11861 Stockholm, Sweden) is approved under condition that the measures described by the EHF for the EHF Champions League season 2006/2007 are implemented accordingly. In addition recommendations are mentioned.

Details/remarks & further procedure

The following problem points could be figured out together with the club Hammarby.

1./ Security spaces

The security standards between the spectator's area and the playing court lines are too short (substitution area too narrow).



Measures to be taken:

- → Removal of approximately two rows of spectators' seats behind the judges table area and of the fix grand stands on the small side left to the table in order to achieve the minimum security space of 44x24 m:
 - Required free space (base area) 2 m behind the outer goal lines and
 2,5 m behind the side line in the substitution area;
 - Wooden walls, which border off the spectators are to be moved backwards after the seats are removed;
 - Directly behind the advertising boards (without regard whether vertical boards or triangle boards are used) a service corridor shall be established (walkway behind ads on all four sides);

Recommendable measures:

→ Gain as much space as possible around the playing field (base area) – more than 44x24 will be an advantage for the future.

2./ TV set-up

No TV platforms are permanently installed in the playing hall, but required for each EHF Champions League event.

Measures to be taken:

→ TV plat-forms have to be installed in good time prior to each EHF Champions League event (permanent platforms make the use of the area/infrastructure easier).

FURTHER RECOMMENDABLE MEASURES:

→ Spectator's capacity

The EHF Champions League events will be further developed in the future and therefore it is to be expected that standards concerning minimum capacity for arenas being used for EHF Champions League competitions will be fixed in the future. The same is valid for subsequent Champions League phases (1/8 finals,



1/4 finals, semi-finals and finals) – definition of minimum capacities based on the competitions phase (compare CL regulations) during the season.

→ Permanent Fax/Telephone lines, Wireless LAN inside the arena

In order to provide the media and other service partner with optimised working conditions inside the arena sufficient capacities of technical equipment (permanent fax/telephone lines, wireless access, power supply, etc.) will be of importance.

→ Flooring with handball lines only

A combination of lines of different sports spoils the TV picture and has a negative impact on the appearance of the event and the recognition of the sport by the public. Therefore a flooring with handball lines only is highly recommendable.

The measures described in this document refer to those, which will be of relevance for the permanent infrastructure in Ericsdaldshallen. As you are aware of individual adaptations and the set-up for the Champions League matches will be necessary in any case for each match.

Please provide us with your concept for the implementation of the details referred to as soon as possible.

We are looking forward to the further cooperation and remain with.

Kind regards,

EUROPEAN HANDBALL FEDERATION

Related Ressourcing